

Release Notes

Product Name: RC-206, RC-208

Current Version:

Type	Number	Date
Firmware	4.0.45.49251	October 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: October 2018

Reference: 13165

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-206	N/A	N/A	N/A
RC-208	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codedependency with Other Products and Software:

Product Name	Comments
K-Config	

- There is no codedependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: RC-206, RC-208

Current Version:

Type	Number	Date
Firmware	4.0.45.49251	October 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: October 2018

Reference: 13165

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/RC-206>

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1428, 1429	RS-232 Tx/Rx: When performing a load RS-232 communication test, one of every thousand characters may be lost (Rx+Tx simultaneously) and cause sending/receiving command failure.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com